


Pax Bolt Down and Ganging Assembly Instructions

Model Number PX11-XXX, PX13-XXX, PX40-XXX,PX42-XXX



SCALE 1:3

Page 1 of 1

www.norix.com • TEL 800 234-4900

Rev. B - 07/25/24

091-1029

SCALE 1:8

Assembly			nstallation. If your shipment does not match the parts list, please contact Norix Customer Service any time without an obligation to owners of previously sold products.	at 800-234-4900.
Parts List (Bolt Down)				Tools Needed
ITEM	QTY.	PART NUMBER	DESCRIPTION	Low RPM Variable Speed Drill
Α	1	PXYY-XXX	Pax Product	(071-001) Torx in Pin® T-27
В	2	011-081	Pax, Bolt Down Plate	·
С	4	021-080	Screw, Machine 1/4-20 X .75, BH, T-in-P, T-27	
Parts List (Ganging)				$\left(C\right) _{-}$
ITEM	QTY.	PART NUMBER	DESCRIPTION	
Α	1	PX11-XXX, PX13-XXX, PX40-XXX	Pax Product (Except PX42-XXX)	B
Е	1	011-080	Pax, Ganging Plate	
С	4	021-080	Screw, Machine 1/4-20 X .75, BH, T-in-P, T-27	
D	4	026-006	Washer, Flat, 11-32 ID x 3-4 OD x .050 18-8 SST	
1. HA AND 2. FIN ANC	AND TH INTO F IISH TIC HOR LO	READ SCREW (C) PAX PRODUCT (A SHTING (Detail C) DCATIONS.	THROUGH BOLT DOWN PLATE (B)) AS SHOWN IN DETAIL A.), PLACE ON GROUND AND MARK	DETAIL A SCALE 1 : 8
DOW PROI Bolt	N, A C DUCTS ED DO	SANGING PLATES AS SHOWN BELO WN AFTER EVERY	AX PRODUCT IS BEING BOLTED SHOULD BE USED ON THE MIDDLE W. THE END PRODUCTS ARE THIGN IS GANGED TOGETHER.	
SHO\	E (E) A WN IN	Not Available for READ SCREW THE WASHER (D) THRO ND INTO PAX PRO DETAIL B. SHTING.	Ottoman PX42): ROUGH (C), DUGH GANGING DDUCT (A) AS	A
(E 07/25/	DETAIL B		DETAIL C