





## Pax Bolt Down and Ganging Assembly Instructions



www.norix.com • TEL 800 234-4900

**Model Number**  
**PX11-XXX, PX12-XXX,**  
**PX40-XXX, PX42-XXX**

**Assembly Notes:** Norix is not responsible for any damage due to improper installation. If your shipment does not match the parts list, please contact Norix Customer Service at 800-234-4900. Norix reserves the right to modify design specifications at any time without an obligation to owners of previously sold products.

Parts List (Bolt Down)				Tools Needed
ITEM	QTY.	PART NUMBER	DESCRIPTION	Low RPM Variable Speed Drill (071-001) Torx in Pin® T-27
A	1	PXYX-XXX	Pax Product	
B	2	011-081	Pax, Bolt Down Plate	
C	4	021-080	Screw, Machine 1-4-20 X .75, BH, Torx in Pin® T-27	
Parts List (Ganging)				
ITEM	QTY.	PART NUMBER	DESCRIPTION	
A	1	PXYX-XXX	Pax Product	
E	1	011-080	Pax, Ganging Plate	
C	4	021-080	Screw, Machine 1-4-20 X .75, BH, Torx in Pin® T-27	
D	4	026-006	Washer, Flat, 11-32 ID x 3-4 OD x .050 18-8 SST	


### Bolt Down:

1. HAND THREAD SCREW (C) THROUGH BOLT DOWN PLATE (B) AND INTO PAX PRODUCT (A) AS SHOWN IN DETAIL A.
2. FINISH TIGHTING (Detail C), PLACE ON GROUND AND MARK ANCHOR LOCATIONS.


**NOTE:** IF MORE THAN ONE PAX PRODUCT IS BEING BOLTED DOWN, A GANGING PLATE SHOULD BE USED ON THE MIDDLE PRODUCTS AS SHOWN BELOW. THE END PRODUCTS ARE BOLTED DOWN AFTER EVERYTHING IS GANGED TOGETHER.

### Ganging:

1. HAND THREAD SCREW THROUGH (C), THROUGH WASHER (D) THROUGH GANGING PLATE (E) AND INTO PAX PRODUCT (A) AS SHOWN IN DETAIL B.
2. FINISH TIGHTING.



DETAIL B  
SCALE 1 : 8



DETAIL C  
SCALE 1 : 3