## Hondo Nuevo Ganging Kit for Steel Bases Assembly Instructions

## Model Number: C011-025

www.norix.com • TEL 800 234-4900

**Dr** 

RNIT

Assembly Notes: Norix is not responsible for any damage due to improper installation. If your shipment does not match the parts list, please contact Norix Customer Service at 800-234-4900. Norix reserves the right to modify design specifications at any time without an obligation to owners of previously sold products.

PARTS LIST			
ITEM NO.	QTY.	PART NUMBER	DESCRIPTION
А	1	011-029	Hondo Nuevo Gang Brkt, Steel Base, Female
В	1	011-030	Hondo Nuevo Gang Brkt, Steel Base, Male
С	2	021-017	Screw, Machine, 5/16-18 X 1/2", BH, Pin in Torx® T-40, Steel, Zinc
D	2	025-011	Lock Washer, Split, 5/16", Zinc
Е	2	026-006	Washer, Flat, 11/32" ID X 3/4" OD, SS
	1	071-002	Pin in Torx® Driver T-40

## Read and understand instructions completely before assembly.


R

**1.** Turning the furniture units upside down will simplify assembly. Typically, the bracket with the narrow slot (A) should be attached to the unit that will be on the left.

Assemble bracket (A) to the unit using (1) Screw (C), (1) Lock Washer (D), and (1) Flat Washer (E).

Note: Bracket (B) has a slot for the attachment screw. Depending on the size of the unit, the attachment screw may end up being located at either end of the slot or in the middle (see figure below). After assembling bracket (A), adjust bracket (B) to align with bracket (A) so that the tab will fit into the slot.

**2.** Assemble bracket (B) to the other unit using (1) Screw (C), (1) Lock Washer (D), and (1) Flat Washer (E).





Tools Needed Variable Speed Drill Pin in Torx® Driver T-40

В

Front

В

D

E

D

Е

Ò

6

Q)