

Ballasting Instructions for Mix-Up Product

www.norix.com • TEL 800 234-4900

Assembly Notes: Norix is not responsible for any damage due to improper installation. If your shipment does not match the parts list, please contact Norix Customer Service at 800-234-4900. Norix reserves the right to modify design specifications at any time without an obligation to owners of previously sold products.

PARTS LIST				
PARIS LIST				
ITEM	QTY.	PART NUMBER	DESCRIPTION	
Α	1	011-040	Plug, Threaded, 4 in., TONIK	
В	2	022-010	Screw, Self-Drilling, 8-18 X 0.50" L., SS	


Tools Needed
DrillPin-In-Torx® Bit, T-20


Products	Recommended Ballast (lbs.)
Mix-Up, Round	14
Mix-Up, Large Round	70
Mix-Up, Square	20
Mix-Up, Rectangular	50
Mix-Up, Wedge	14

Note: These instructions apply to all Mix-Up product with a Threaded Plug.


- 1. Turn product upside down and place on a protected surface to prevent from getting dirt.
- 2. Remove the Threaded Plug (A).
- 3. Fill product with ballast material.
 Clean dry pea gravel is recommended (not provided). For the proper amount of ballast, see Chart.
- 4. After adding ballast, re-install the Threaded Plug ensuring that it is securely tightened.
- 5. Secure the Plug using the supplied #8-18 X .50" self-drilling screws **(B)** in the locations shown below. Do not overtighten.

Turning the product upright may require two people.





Self-drilling screw location



Rev. A - 12/19/2017 091-916

Page 1 of 1