



Received:09/04/2013	Completed:09/06/2013	Letter: C2	AA	P.O.#:	Test Report #:	2-98536-2-
---------------------	----------------------	------------	----	--------	----------------	------------

Client's Identification	Product Description: Chair, Hondo, Lounge, Lagoon.
-------------------------	--

Tested For: **Jim Sanders**

Norix Group, Inc,
1880 West Hawthorne Lane
West Chicago, IL 60185

Key Test: BS 5852 Source#7 (Crib 7) - Clause 11 450

Tel: 1-(630)-957-4411

Ext:

Fax: 1-(630)-231-4343

PC: 24H SM/jd

TEST PERFORMED:

British Standard BS 5852 : 2006 - Methods of Test for Assessment of the Ignitability of Upholstered Seating by Smouldering and Flaming Ignition Sources;
Clause 11 - Methods of Test for the Ignitability of Upholstery Composites

IGNITION SOURCE:

#7 (126 gram wooden crib)

TEST RIG:

[] Small; [] Large; [x] Fire Room Test - Actual Item

TEST ITEM COMPOSITE:

Cover Material: (see client's Identification section above)

Interliner (Fire Blocking) Material: (see client's Identification section above)

Filling Material: (see client's Identification section above)

COVER FABRIC WATER SOAKED PRIOR TO TESTING: [] YES; [] NO; [x] MOLDED UNIT - NOT APPLICABLE

BRIEF DESCRIPTION OF TEST:

Test cushions are placed in a test frame to form a mockup of an upholstered chair. A 126 gram wooden crib is placed on the mockup so that it is in contact with the seat bottom and seat back. The crib is ignited. Test observations are made and results are recorded.



Received:09/04/2013	Completed:09/06/2013	Letter: C2	AA	P.O.#:	Test Report #:	2-98536-2
Client's Identification	Product Description: Chair, Hondo, Lounge, Lagoon.					
Tested For: Jim Sanders Norix Group, Inc, 1880 West Hawthorne Lane West Chicago, IL 60185				Key Test: BS 5852 Source#7 (Crib 7) - Clause 11 450 Tel: 1-(630)-957-4411 Ext: Fax: 1-(630)-231-4343		

ABBREVIATIONS WHICH MAY BE USED:

N/O = Not observed.

NT = Not tested.

EC = Escalating combustion (unsafe); test extinguished by technician at time noted.

COMMENTS: None.

CONCLUSION: The above Results indicate that:

☒ Ignition Criteria did not occur (favourable)

☐ Ignition Criteria did occur (unfavourable)

Note: The subject test measures whether or not ignition occurs. The codes speak in terms of ignition resistance. Therefore, the conclusion "Ignition Criteria did not occur" is a favourable conclusion; and "Ignition Criteria did occur" is not a favourable conclusion.

CERTIFICATION: I certify that the above results were obtained after testing specimens in accordance with the procedures and equipment specified by BS 5852:2006.

AUTHORIZED SIGNATURE
THE GOVMARK ORGANIZATION, INC. / ec

qib

SEP 13 2013

Robert I. Brown

(Page 4 of 4)