

# NORIX GROUP INC. TEST REPORT

## **SCOPE OF WORK**

CALIFORNIA TECHNICAL BULLETIN 116-2019 - FLAME RETARDANCE OF UPHOLSTERED FURNITURE TEST ON PRODIGY BED PRD100-XXX

# **REPORT NUMBER**

104238836SAT-003C

# TEST DATE(S)


02/18/2020

## **ISSUE DATE**

02/24/2020

## **PAGES**

4





16015 Shady Falls Road Elmendorf, Texas 78112

Telephone: 210-635-8100 Facsimile: 210-635-8101 www.intertek.com/building

## TEST REPORT FOR NORIX GROUP INC.

Report No.: 104238836SAT-003C

Date: 02/24/2020

#### **REPORT ISSUED TO**

#### **NORIX GROUP INC.**

1800 West Hawthorne Lane Suite North West Chicago, IL 60185

## **SECTION 1**

## **SCOPE**

Intertek Building & Construction (B&C) was contracted by NORIX GROUP INC., 1800 West Hawthorne Lane Suite North, West Chicago, IL 60185 to perform testing in accordance with California Technical Bulletin 116-2019, Requirements, Test Procedure and Apparatus for Testing the Flame Retardance of Upholstered Furniture Test on their PRODIGY BED PRD100-XXX. Results obtained are tested values and were secured by using the designated test method. Testing was conducted at Intertek B&C test facility in Elmendorf, Texas. This report does not constitute certification of this product nor an opinion or endorsement by this laboratory.

#### For INTERTEK B&C:

Title:
Technician 3
Title:

Signature:

Date:

O2/24/2020

Theodore Salazar
REVIEWED BY:
Servando Romo
Project Manager

Signature:

Date:

O2/26/2020

Date:

O2/26/2020

#### **SECTION 2**

# **TEST METHOD(S)**

The specimen was evaluated in accordance with the following:

**California Technical Bulletin 116-2019 -** Requirements, Test Procedure and Apparatus for Testing the Flame Retardance of Upholstered Furniture

#### **SECTION 3**

## LIST OF OFFICIAL OBSERVERS

NAME	COMPANY	
Theodore Salazar	Intertek B&C	

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Page 2 of 4 GFT-OP-10c



16015 Shady Falls Road Elmendorf, Texas 78112

Telephone: 210-635-8100 Facsimile: 210-635-8101 www.intertek.com/building

## TEST REPORT FOR NORIX GROUP INC.

Report No.: 104238836SAT-003C

Date: 02/24/2020

#### **SECTION 4**

#### **TEST PROCEDURE**

Three cigarettes of a standard description are lit and placed on each of all horizontal surfaces (including smooth, welted, quilted, decking, tops of arms and backs, tufted, or button locations plus all crevices created by the orientation of seat cushions and furniture side and back panels) and covered with a 6" x 6" sheet of cotton bed sheeting material. If a cigarette extinguishes before burning its full length, a fresh one is applied to a similar location on a different portion of the furniture. Each furniture surface shall be tested until either (a) three cigarettes have burned their full length, (b) three cigarettes have extinguished before burning their full length, or (c) one cigarette has resulted in failure.

#### **SECTION 5**

## **TEST SPECIMEN DESCRIPTION**

SAMPLE ID	PRODIGY BED PRD100-XXX		
DESCRIPTION	Consisted of an open chest. The sample was a sand color.		
SPECIMEN SELECTION	Sample was submitted to Intertek directly from the client. Sample		
SPECIIVIEN SELECTION	was not independently selected for testing.		
RECEIVED DATE	02/13/2020 (Samples received in good condition)		
INTERTEK SAMPLE	SAT2002131100-001		
TRACKER NUMBER			

## **SECTION 6**

#### **TESTING RESULTS AND CRITERIA**

ITEM	OBSERVATION
Obvious Flaming	None
Maximum Char Distance from Cigarette	0.25 inches

An article of upholstered furniture fails to meet the provisions of law if any of the following conditions occur: A.) If obvious flaming combustion occurs; B.) If a char develops more than two inches in any direction from the cigarette, measured from its nearest point.

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Page 3 of 4 GFT-OP-10c



16015 Shady Falls Road Elmendorf, Texas 78112

Telephone: 210-635-8100 Facsimile: 210-635-8101 www.intertek.com/building

#### TEST REPORT FOR NORIX GROUP INC.

Report No.: 104238836SAT-003C

Date: 02/24/2020

## **SECTION 7**

## **CONCLUSION**

Intertek has conducted testing for NORIX GROUP INC. on the PRODIGY BED PRD100-XXX, to evaluate the flame retardance of upholstered furniture. Following the standard methods of California Technical Bulletin 116-2019, Requirements, Test Procedure and Apparatus for Testing the Flame Retardance of Upholstered Furniture.

Based on the results of the testing as indicated above, the sample **PRODIGY BED PRD100-XXX**, **MET** the requirements of California TB 116-2019.

The conclusions of this test report may not be used as part of the requirements for Intertek product certification. Authority to Mark must be issued for a product to become certified.

#### **SECTION 8**

#### **REVISION LOG**

REVISION #	DATE	PAGES	REVISION
0	02/24/2020	N/A	Original Report Issue
"			

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Page 4 of 4 GFT-OP-10c