

Assembly Notes: Norix is not responsible for any damage due to improper installation. If your shipment does not match the parts list, please contact Norix Customer Service at 800-234-4900. Norix reserves the right to modify design specifications at any time without an obligation to owners of previously sold products.

PARTS LIST

ITEM	QTY.	PART NUMBER	DESCRIPTION
A	1	011-040	Plug, Threaded, 4 in., TONIK
B	2	022-010	Screw, Self-Drilling, 8-18 X 0.50" L., SS

Tools Needed



DrillPin-In-Torx® Bit, T-20

Products	Factory Ballast (lbs.)	Max Ballast (lbs.)
Mix-Up, Round	15	15
Mix-Up, Large Round	50	50
Mix-Up, Square	15	15
Mix-Up, Rectangular	35	50
Mix-Up, Wedge	15	15

NOTE: THESE INSTRUCTIONS APPLY TO ALL MIX-UP PRODUCT WITH A THREADED PLUG.

1. TURN PRODUCT UPSIDE DOWN AND PLACE ON A PROTECTED SURFACE TO PREVENT FROM GETTING DIRT.
2. REMOVE THE THREADED PLUG (A).
3. FILL PRODUCT WITH BALLAST MATERIAL. CLEAN DRY PEA GRAVEL IS RECOMMENDED (NOT PROVIDED). FOR THE PROPER AMOUNT OF BALLAST, SEE CHART.
4. AFTER ADDING BALLAST, RE-INSTALL THE THREADED PLUG ENSURING THAT IT IS SECURELY TIGHTENED.
5. SECURE THE PLUG USING THE SUPPLIED #8-18 X .50" SELF-DRILLING SCREWS (B) IN THE LOCATIONS SHOWN BELOW. DO NOT OVER-TIGHTEN.

TURNING THE PRODUCT UPRIGHT MAY REQUIRE TWO PEOPLE.



Self-drilling
screw location

