




Ripple Chair Bolt Down Assembly Instructions

Model Number
RPXX-XXX-MXXX-B



www.norix.com • TEL 800 234-4900

Assembly Notes: Norix is not responsible for any damage due to improper installation. If your shipment does not match the parts list, please contact Norix Customer Service at 800-234-4900. Norix reserves the right to modify design specifications at any time without an obligation to owners of previously sold products.

Parts List				Tools Needed
ITEM	QTY.	PART NUMBER	DESCRIPTION	
A	1	RPXX-XXX	Ripple Chair	Low RPM Variable Speed Drill
B	1	RPXXB-MXXX	Ripple, Plinth Molded Base	Pin in Torx Bit, T-25
C	4	026-008	Nut/Washer Assembly, 3/8"-16, Zinc, Thd. Lk.	
D	4	029-044-03	Plate, Bolt Down, Bengal Silver	
E	(12)	021-144	Screw, #10-16 X 1.5"L, BH, P-in-T T-25, Blk. Ox.	

1. Unscrew all Screws (E) and remove Molded Base

