

TEST REPORT

The Intertek logo consists of the word "Intertek" in white, sans-serif font, centered within a dark blue rounded rectangle.

REPORT NUMBER: 101398396SAT-001J

ORIGINAL ISSUE DATE: 11/15/2013

REVISED DATE: None

EVALUATION CENTER

Intertek Testing Services NA Inc.
16015 Shady Falls Road
Elmendorf, Texas 78112

RENDERED TO

**Norix Group Inc
1000 Atlantic Drive
West Chicago, IL 60185**

PRODUCT EVALUATED: Arm Sectional

EVALUATION PROPERTY: Peak Heat Release Rate, and Total Heat Release,

Report of Testing Hondo Nuevo Right Arm Sectional for compliance with the applicable requirements of the following criteria:

- **California Bureau of Home Furnishings Technical Bulletin 133, Flammability Test Procedure for Seating Furniture for Use in Public Occupancies**
- **ASTM E1537, Standard Test Method for Fire Testing of Upholstered Furniture, and**
- **UL 1056, Fire Test of Upholstered Furniture**

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

1 Table of Contents

1	Table of Contents	2
2	Abstract	3
3	Introduction	4
4	Test Samples	4
	4.1. SAMPLE SELECTION.....	4
	4.2. SAMPLE AND ASSEMBLY DESCRIPTION	4
5	Testing and Evaluation Methods	4
6	Testing and Evaluation Results.....	5
	6.1. RESULTS AND OBSERVATIONS	5
7	Conclusion	6
	APPENDIX A	7
	APPENDIX B	9
	APPENDIX C	12
	REVISION SUMMARY	14

2 Abstract

Intertek Testing Services NA has conducted testing for **Norix Group Inc**, on the following product:

Test Sample: **Hondo Nuevo Right Arm Sectional**

Test Standard: **TB 133, ASTM E1537 and UL 1056.**

Test Date: **November 14, 2013**

Test Sponsor: **Norix Group, Inc**

Test Results: **Met Requirements**

Refer to Sections 6 & 7 for complete results