



www.norix.com • TEL 800 234-4900


# Hondo Nuevo Plinth Base to Rocker Base Replacement Instruction (Arm Chair or High Back ONLY)

## ROCKER KIT C011-057-XXX

Model Number  
HN800-YYY/HN850-800-ZZZ  
OR  
HN880-YYY/HN850-800-ZZZ

TO

HN800-YYY/HN851-800-ZZZ  
OR  
HN880-YYY/HN851-800-ZZZ



Assembly Notes: Norix is not responsible for any damage due to improper installation. If your shipment does not match the parts list, please contact Norix Customer Service at 800-234-4900.  
Norix reserves the right to modify design specifications at any time without an obligation to owners of previously sold products.

### Parts List

ITEM	QTY.	PART NUMBER	DESCRIPTION
A	1	HN851-800-ZZZ	Hondo Nuevo Rocker Base
B	26	021-166	Screw, #10 X 1", BH, Pin in Torx T-25

### Tools Needed

Low RPM Variable Speed Drill  
071-007 - Pin in Torx Bit, T-25

PUT CHAIR UPSIDE DOWN ON CLEAN SURFACE.  
REMOVE ALL SCREWS.

LOCATE AND CENTER NEW ROCKER  
BASE WITH MARK "FRONT" FACING  
TO FRONT OF CHAIR.  
SECURE ROCKER BASE (A) WITH NEW OR  
USED SCREWS (B) AT DIMPLED LOCATIONS.

